

UNCLASSIFIED

AD 257 327

*Reproduced
by the*

ARMED SERVICES TECHNICAL INFORMATION AGENCY
ARLINGTON HALL STATION
ARLINGTON 12, VIRGINIA



UNCLASSIFIED

NOTICE: When government or other drawings, specifications or other data are used for any purpose other than in connection with a definitely related government procurement operation, the U. S. Government thereby incurs no responsibility, nor any obligation whatsoever; and the fact that the Government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use or sell any patented invention that may in any way be related thereto.

CATALOGED BY ASTIA
AS AD NO. 257 327

61-3-3
XEROX

TALOS STRUCTURAL FIRING TEST
ABOARD THE USS LITTLE ROCK (CLG-4)

J. W. Loving
T. J. Dodson
C. W. Fischler
P. E. Wine



U. S. NAVAL WEAPONS LABORATORY
DAHLGREN, VIRGINIA

ASTIA
SEARCHED
SERIALIZED
INDEXED
MAY 1961

Date: 11 MAY 1961

U. S. Naval Weapons Laboratory
Dahlgren, Virginia

TALOS Structural Firing Test
Aboard the USS LITTLE ROCK (CLG-4)

by

J. W. Loving
T. I. Dodson
C. W. Fischler
P. E. Wine

Weapons Development and Evaluation Laboratory

NWL REPORT NO. 1751

Task Assignment
NO 512-535/55008/69-064

11 May 1961

Released to ASTIA without restriction or limitation.

CONTENTS

	<u>Page</u>
Abstract	ii
Foreword	iii
Introduction	1
Test Procedures	1
Results and Discussion	6
1. Camera Coverage	6
2. Temperature Measurements	6
3. Toxic Gas Sampling	7
4. Sound Pressure Levels	7
5. Pressure Measurements	8
6. Strain Measurements	8
7. Flame Indicators	9
8. Structural Damage	9
Conclusions	9
Recommendations	10
References	11
Appendices:	
A. Detailed Test Objectives	
B. Distribution	

- - - - -

Figures:

1. Microphone Locations
2. Pressure and Strain Gauge Locations, Missile House
3. Pressure Gauge Locations for Test 6
4. Pressure Gauge Locations for Test 5
5. Temperature versus Time Curve
6. Strain Record for Test 3
7. Flame Indicator Locations
- 8-20. Views Showing Damage Incurred

Tables:

1. Camera Details
2. Air Temperature Measurements
3. Results of Gas Sampling Tests
4. Maximum Noise Level Measurements
5. Pressure Measurements on Missile House
6. Pressure Measurements on the Deck
7. Flame Indicator Results for all Rounds

ABSTRACT

Six TALOS Mk 11 Mod 2 boosters with concrete slugs were fired aboard the USS LITTLE ROCK (CLG-4) to investigate the adequacy of the protection for the TALOS launching system personnel against blast effects and to determine the effects of the booster blast on the ship's structure. The test vehicles were fired at various angles such that the exhaust stream was directed at areas where damage, flame, or toxic gas leakage had occurred during the structural firing tests aboard the USS GALVESTON (CLG-3). These tests were also utilized to evaluate the design changes in the ship's structural components that were necessitated by the results of the GALVESTON tests. Measurements were made of pressures in the exhaust stream, structural strains, toxic gas concentrations, noise levels, flame penetrations at door seals and temperature changes inside the ship. High-speed motion pictures were taken on all tests.

The results indicated gas and flame leakage around the blast doors, toxic gas leakage into the ventilation systems, and minor structural damage to equipment mounted on the sides of the missile house and the main deck. A detailed description of all data obtained and ship damage incurred is included in this report.

FOREWORD

This is the final report on the TALOS Structural Firing Tests Aboard the USS LITTLE ROCK (CLG-4) conducted under BUWEPS Task Assignment NO 512-535/55008/69-064 Amendments No. 1 and 2 of 17 June 1959 and 10 August 1960, respectively. These tests were performed as part of the BUWEPS Ship Qualification Tests for the USS LITTLE ROCK (CLG-4) conducted by the Applied Physics Laboratory of the John Hopkins University (APL/JHU) for the Bureau of Naval Weapons and in accordance with Test 8 of the test program, reference (a). These tests were conducted to determine the effects of the TALOS booster blast on the ship's structure, and to establish the adequacy of protection for the TALOS launching system personnel against blast effects.

This report was reviewed by the following members of the Weapons Development and Evaluation Laboratory:

J. J. WALSH, Head, Physical Projects Section
D. C. ROSS, Head, Experimental Branch
H. R. PRYOR, Head, Development Division
D. W. STONER, Deputy Director
M. W. WHITAKER, Captain, USN, Director

APPROVED FOR RELEASE:

/s/ R. H. LYDDANE
Technical Director

INTRODUCTION

Before assigning personnel to operational areas in the proximity of the TALOS launcher, it was necessary to determine whether the structures provide adequate protection from the booster blast. In order to determine the effects of the booster blast on the ship's structure, six TALOS Launcher Test Vehicles (LTV), each composed of a Mk 11 Mod 2 booster with a concrete slug, were fired at various angles such that the exhaust stream was directed at areas where damage, flame or toxic gas leakage had occurred during the structural firing tests aboard the USS GALVESTON (CLG-3). These tests also served to evaluate the design changes in the ship's structural components that were dictated by the results of the blast tests conducted aboard the GALVESTON. Tests were also conducted to determine the adequacy of the door seals, ports, and equipment exposed to the direct booster blast. Detailed test objectives are given in the test plan, reference (a), and repeated in Appendix A.

The tests also determined the effects of the booster blast on an instrumented simulated emergency igniter injector unit for the TALOS launching system. The results of the igniter injector unit tests were reported in reference (b).

On board the USS LITTLE ROCK (CLG-4) were instrumentation teams for measuring toxic gas concentrations, noise pressure levels, structural strains, pressures in the exhaust stream, structural accelerations and temperature changes inside ship compartments, for providing high-speed photographic coverage, and for observing the extent of flame entrance at door seals. The instrumentation was moved for each test in order to make all measurements in the same configuration with respect to the impingement areas. The detailed test results are grouped according to type of measurement, rather than by test. This arrangement avoids repeated references to the type of measurement considered.

An assist ship, USS SHAKORI (ATF-162), was in close company and furnished over-all high-speed photographic coverage of the booster exhaust stream.

TEST PROCEDURES

The instrumentation was installed and operated by Naval Weapons Laboratory personnel with the assistance of members of the ship's company assigned to the various groups. The equipment used to record pressure, strain and temperature was installed in a 28' x 8' instrumentation trailer located on the starboard side of the 02 level at approximately

Frame 95. Signal cables were connected between the instrumentation trailer and the transducers, which were located throughout the after part of the ship at the areas under test. For each test a TALOS Mk 11 Mod 2 booster with a concrete slug was launched from either the "A" rail or the "B" rail of the Mk 7 Mod O Guided Missile Launcher.

The launcher angles, impingement areas, and the sequence in which the tests were conducted are indicated in the table below:

<u>Test No.</u>	<u>Date</u>	<u>Rail Loaded</u>	<u>Train</u>	<u>Elevation</u>	<u>Impingement Area</u>
1	8-29-60	A	144°44'	14°	Missile House Observation Port.
2	8-29-60	B	156°05'	12°30'	Slanting bulkhead two feet aft of Door (D-1-119-2).
3	8-29-60	A	207°59'	10°53'	Main deck Frame 121 starboard side.
4	8-30-60	B	220°58'	10°	Starboard Blast Door.
6	8-30-60	A	39°	43°	Deck aft of launcher.
5	8-30-60	A	145°	75°	Deck forward of launcher.

The tests were conducted as part of the BUWEPS Ship Qualification Tests for guided missile ships and were fired in the Virginia Capes Operational Area.

After each test a description of the damage was recorded, and damaged areas were photographed. The test data were returned to the Naval Weapons Laboratory for detailed analysis and reporting.

The procedures followed by the different groups in obtaining each type of measurement or observation are described in the following paragraphs:

1. CAMERA COVERAGE

Camera coverage was arranged to provide information on structural damage, for observing extent of flame entrance at door seals and to document the other test instrumentation on all tests. Details for each camera including its location, type, speed and coverage are included in Table 1.

2. TEMPERATURE MEASUREMENTS

The air temperature was monitored in the missile house, and in other operational areas that would be manned during missile launchings, to record any changes in temperature attributable to the firing of the boosters.

Iron-constantan thermocouples fabricated from No. 24 Brown and Sharpe gauge thermocouple wire and connected to a recording potentiometer were used to monitor the temperature. The equipment was capable of indicating a temperature change of one degree Fahrenheit. The thermocouples were installed in the areas indicated in the table below:

<u>Location</u>	<u>Test No.</u>
Wing and Fin Assembly Area	1
Port Checkout Area	2
Starboard Checkout Area	3
Wing and Fin Assembly Area	4
After Repair Station No. 3	5
After Repair Station No. 3	6

The recorder was operated over a period beginning 5 minutes before firing and ending 15 minutes after firing the boosters.

3. TOXIC GAS SAMPLING

Shipboard toxicity tests were conducted to determine the presence and the concentrations of noxious gas leakage into the interior of the ship. Among the expected products of combustion were carbon monoxide, lead, and oxides of nitrogen.

Air samples were collected at the completion of each test with Mine Safety Appliance (M-S-A) gas sampling equipment to determine the presence and concentrations of these substances. The types of gas samplers employed are indicated in the following table.

<u>Gas</u>	<u>Sampler</u>
Carbon Monoxide	M-S-A Tester, Type By-47133 M-S-A Indicator, Type DS-43823
Oxides of Nitrogen	M-S-A Detector, Type 83100 Drager-Gas Detector
Lead	M-S-A Lead-In-Air Detector

Lead concentrations were also determined by using a motor operated vacuum pump which collected air samples in a solution for laboratory analysis.

Before each test air samples were collected to determine if lead was present from the previous test.

4. SOUND PRESSURE LEVELS

Sound pressure level measurements were made in areas adjacent to the missile launcher to provide information on the high intensity noise levels generated by the firing of the TALOS booster. This information will be furnished to BUMED for determination of physiological hazards to the personnel manning these areas.

The outputs from condenser microphones employed for obtaining the sound pressure level measurements were recorded on magnetic tapes and later analyzed with an audio frequency spectrometer. Sound level meters were also employed to obtain peak level readings for on-the-spot evaluation of the sound pressure levels generated by the firing of the boosters. The microphones were located for each test as indicated in Figure 1 and identified by Table 4.

Before each test the microphone systems were calibrated by applying a pure 400 cycle tone at 121 db with respect to the reference level, 0.0002 dynes/cm².

5. PRESSURE MEASUREMENTS

Pressure measurements were obtained during Tests 2 and 3 to determine the forces acting on the sides of the missile house from low angle firings which impinged directly on or along side of the deck house. Pressure measurements were also obtained during Tests 5 and 6 to determine the forces acting on the main deck from high angle firings which impinged directly on the main deck.

Unbonded strain gauge transducers were employed to obtain the pressure measurements. The outputs from the transducers were recorded on an electromagnetic oscillograph using galvanometers with sensitivities of 10.7 microamperes per inch of deflection.

The pressure measurements were obtained with the gauges sensing the pressure through holes normal to the surface of the structure. The locations of the holes in the sides of the missile house are indicated in Figure 2. The holes through the main deck were located within the area formed by the intersection of the supersonic cone of the exhaust stream with the main deck. Figures 3 and 4 represent the arrangement of the holes in the main deck for Tests 5 and 6.

6. STRAIN MEASUREMENTS

Strain measurements were made during Tests 2 and 3 to determine the effect of the booster blast on major structural components of the missile house under various types of loading. The LTV in Test 2 was fired at such an angle that the exhaust stream impinged directly on the slanting bulkhead of the missile house. Test 3 was arranged so that the exhaust stream impinged on the main deck approximately three feet out-board of the bulkhead.

Resistance strain gauges were employed to obtain the strain measurements. The strain gauges were bonded at equally spaced intervals on each of the vertical stiffeners at Frame 120 on the port and starboard sides of the missile house as indicated in Figure 2. The outputs from the strain gauges were recorded on an electromagnetic oscillograph using galvanometers with sensitivities of 10.7 microamperes per inch.

7. ACCELERATION MEASUREMENTS

An attempt was made to obtain acceleration measurements during Tests 2 and 3 to provide information about the acceleration forces tending to dislodge the blow-out patches at Frame 109 on the port and starboard sides of the missile house. However, the acceleration measurements obtained during the conduct of Test 2 indicated that high frequency transients overloaded the amplifiers in the recording system. It was not practicable to obtain acceleration measurements during Test 3 because the accelerometer signals were obscured by 60-cycle electrical noise induced in the accelerometer recording system.

8. FLAME INDICATORS

Flame indicators were used to provide evidence of flame or hot gas leakage past the seals of doors, hatches, or ports into the interior of the ship. The flame indicators employed were 2-inch squares of rayon-acetate taffeta wine colored cloth, weighing approximately 3 ounces per square yard. This material has an ignition energy of 2 calories per square centimeter according to the government publication of "The Effects of Nuclear Weapons" dated June 1957.

The flame indicators were installed around the interior periphery of the Port and Starboard Blast Doors, the Checkout Compartment Doors (D-1-119-1) and (D-1-119-2), Hatches (H-1-130-1) and (H-1-130-2), and the Observation Port for all of the tests. At the completion of each test the cloth tufts were examined to determine whether any had been displaced, melted, or burned. If any of the tufts showed indication of exposure to hot gases or flame, they were replaced and the location noted.

RESULTS AND DISCUSSION

The structural firing tests were successfully completed on 30 August 1960. No major structural deficiencies were observed during or after the tests. However, there was a large amount of gas and flame leakage around the blast doors, into air vents, and some minor damage to equipment mounted on the sides of the deckhouse and on the main deck. Detailed discussions of the damage incurred and of each type of measurement are included in the following paragraphs.

1. CAMERA COVERAGE

A film report is being prepared for the Bureau of Naval Weapons from the 16mm motion picture film. A series of frames from the 16mm film taken inside of the ship showing flame and smoke entering around the port and starboard blast doors are shown in Figures 10, 11 and 17. Photographic coverage of the damage and of the leakage around the blast doors are shown in Figures 8 through 20.

2. TEMPERATURE MEASUREMENTS

There were no appreciable variations in the temperature of the areas monitored except during Test 4. This maximum temperature rise of 20°F was attributed to the large amount of flame and hot gas leakage

past the seals of the starboard blast door, Figure 17. A temperature versus time curve for Test 4 is shown in Figure 5. The temperature variations obtained during the conduct of the tests are included in Table 2.

3. TOXIC GAS SAMPLING

The concentrations of carbon monoxide, lead and oxides of nitrogen obtained after each test are included in Table 3. The high concentration of lead, 0.40 milligrams per meter³ (mg/m³); observed in the CPO living quarters after conducting Test 3 was attributed to exhaust gases entering the exhaust ventilation system on the main deck. Toxic gases were also detected in the missile house after conducting Tests 1 through 4 as a result of gas leakage around the periphery of the blast doors and the personnel access doors (D-1-119-1) and (D-1-119-2) into the missile checkout compartments. Figures 10, 11 and 17 indicate the severe leakage past the seals of the port and starboard blast doors during the conduct of Tests 1 and 4 respectively.

Information on toxic gases in this report will be furnished to BUMED for evaluation of the hazards to personnel. The threshold limits¹ of toxicity for carbon monoxide and lead from the Bureau of Medicine and Surgery Instruction 6270.3 are indicated below:

CO	100 parts per million (ppm)
Pb	0.20 mg/m ³

4. SOUND PRESSURE LEVELS

A spectrum analysis of each noise recording was made using a Bruel and Kjaer spectrum analyzer. The output signals from the magnetic tapes were applied successively to each filter of the 1/3 octave spectrum analyzer and a complete time history for each filter was plotted using a high-speed level recorder and the maximum noise level was noted. The maximum (over-all) sound pressure levels for each test which were obtained from the time history curves and from the sound level meters are indicated in Table 4. The more detailed information obtained from the spectral analysis will be furnished to the BUMED for evaluation of the hazards to personnel.

¹Threshold limits should be used only as guides in the control of health hazards and should not be regarded as fine lines between safe and dangerous conditions.

5. PRESSURE MEASUREMENTS

The pressure measurements obtained during the conduct of Tests 2 and 3 indicated pressure variations from -11.0 psig to +14.0 psig acting on the sides of the missile house. The peak positive and negative pressures obtained are indicated in Table 5.

The results of the high angle firings, Tests 5 and 6, indicated pressures up to 270 psig acting on the main deck. The maximum value was obtained in an area bounded by Frames 125 and 126 and longitudinal beams 2 and 3 during Test 5. The peak pressures obtained are listed in Table 6 and the locations identified by Figures 3 and 4.

6. STRAIN MEASUREMENTS

The strain measurements obtained during the conduct of Tests 2 and 3 indicated damped, essentially sinusoidal vibrations at 30 cycles per second. None of the strains indicated excessive loading to the vertical stiffeners. Test 3 produced strains of the greatest magnitude in the starboard vertical stiffener in which the strains varied from 500 microinches per inch of tension (toward the center line of the ship) to 500 microinches per inch of compression. The peak strains measured in the port and starboard vertical stiffeners are indicated in the following table.

Test No.	Gauge Location on Vertical Stiffener	Microinches per inch	
		Tension	Compression
2	Port - Top	110	130
	Center	115	150
	Bottom	190	195
3	Starboard - Top	190	180
	Center	500	500
	Bottom	420	445

The strain gauge located in the center of the starboard vertical stiffener did not return to zero after Test 3, but indicated a residual strain (in tension) of 125 microinches per inch. This residual strain persisted at nearly a constant level until the end of the record period (approximately two seconds after firing). Figure 6 is a reproduction of the strain record for Test 3.

7. FLAME INDICATORS

The results indicate that severe leakage occurred during Tests 1 and 4 around the port and starboard blast doors, respectively. Figures 10, 11 and 17 show the leakage past the blast door seals during the above mentioned tests. The results obtained on all tests are indicated in Table 7 and identified by Figure 7.

8. STRUCTURAL DAMAGE

The firing sequence for this series of tests, as indicated earlier was 1, 2, 3, 4, 6, and 5. Since damage and paint erosion were cumulative, the discussion of the damage has been arranged to follow the sequence in which the tests were conducted. The damage incurred and the flame and smoke leakage around the blast doors resulting from the firing of the boosters are shown in Figures 8 through 20.

The severe leakage of flame, smoke, and hot gases past the seals of both blast doors (Figures 10, 11 and 17) during Tests 1 and 4 would have seriously jeopardized the safety of the operating personnel in Area I of the missile house.

There were minor structural deficiencies noted after several of the firings both on the inside and the outside of the ship. An inspection plate approximately 3 feet by 2 feet for ventilation reheater 167P C-202-L at Frame 115 in the overhead of the CPO mess, sheared the stud bolts holding it to the reheater on three sides during Test 2, Figure 13. Smoke was also observed entering the CPO living space through the exhaust vent during the conduct of Test 3. The damage to the equipment mounted on the sides of the missile house and on the main deck is shown in Figures 8 through 20.

CONCLUSIONS

It is concluded that the damage caused by the blast of the TALOS Mk 11 Mod 2 booster during the structural firing tests was minor. It appears that a redesign of the latching mechanism and the seals for the blast doors, the installation of manually operated closures for the intake and exhaust vents located close to the after edge of the missile house, and the relocation of fragile items on the sides of the missile house and main deck would eliminate most of the damage.

It is further concluded that it is safe to conduct tactical exercises provided that the missile firings are so arranged that the booster blast does not impinge on the face plate of the missile house until further tests have been conducted to insure that the blast doors are flame proof.

No conclusions will be drawn by the Naval Weapons Laboratory regarding the effect of the noise level and toxic gases on personnel, since the information obtained will be furnished to BUMED for further study.

Conclusions regarding the effect of strains and forces on the structural surfaces will be drawn by BUSHIPS.

RECOMMENDATIONS

It is recommended that certain alterations be made on all the CLG-3 class ships. In general this will include removing, where permissible, projections and fittings from the sides of the missile house.

The firings on the LITTLE ROCK indicated that the following items proved to be inadequate to withstand the blast from the boosters. It is recommended that they be redesigned or relocated as noted:

1. Redesign the latching mechanism and the seals of the blast doors to insure that the latter are flame proof.
2. Design and install manually operated closures for the intake and exhaust vents, located close to the after edge of the missile house, to prevent the booster blast from entering the ship through the ventilation system.
3. Redesign the fire hose covers to make them flame proof.
4. Relocate all projections in the after section of the ship, for example, electrical outlet stands.

It is recommended that the blast doors and the checkout compartment doors be tested on all CLG-3 class ships prior to assigning personnel to Area I of the missile house. The test should consist of the booster blast of a fly-away missile impinging on or near the structures.

REFERENCES

- (a) APL/JHU CONF Test Plan TG312-1 for USS LITTLE ROCK (CLG-4) Ship Qualification Test Program
- (b) COMNAVWPNLAB, Dahlgren ltr WDE:JWL:efc 8800/TAL/S of 18 Jan 1961

TABLE 1
CAMERA DETAILS (1)

<u>Test No.</u>	<u>Camera</u>	<u>Location</u>	<u>Speed (frames/sec)</u>	<u>Focal Length of Lens</u>	<u>Coverage</u>	<u>Type of Film</u>
1	16mm Fastax	O4 Level	1000	25mm	Launcher Area and Top of Missile House	Super Anscochrome
	16mm Fastax	Fantail	1000	25mm	Launcher Area.	Super Anscochrome
	70mm Hulcher	Fantail	20	100mm	Launcher Area.	Super Anscochrome
	16mm Mitchell	Wing and Fin Assembly Area	64	17mm	Port Blast Door.	Super Anscochrome
	16mm Fastax	Support Ship	500	3-inch	Launcher Area and Missile House.	Super Anscochrome
	70mm Hulcher	Support Ship	20	15-inch	Launcher Area and Missile House.	Super Anscochrome
2	16mm Mitchell	Port Checkout Area	64	17mm	Door (D-1-119-2).	Super Anscochrome
3	16mm Mitchell	Starboard Check-out Area	64	17mm	Door (D-1-119-1).	Super Anscochrome
4	16mm Mitchell	Wing and Fin Assembly Area	64	17mm	Starboard Blast Door.	Super Anscochrome
5	Same as Test No. 4.					
6	16mm Mitchell	Beneath Hatch (H-1-130-2)	64	17mm	Hatch (H-1-130-2).	Super Anscochrome

(1) The camera details listed for Test No. 1 apply to all tests except for the 16mm Mitchell camera as indicated.

AIR TEMPERATURE MEASUREMENTS

TABLE 2

<u>Test No.</u>	<u>Location</u>	<u>Temperature Before Firing (°F)</u>	<u>Maximum Temperature (°F)</u>	<u>Temperature Rise (°F)</u>	<u>Duration (sec.)</u>
1	Wing and Fin Assembly Area	--	--	--	Instrumentation failure.
2	Port Checkout Area	83	85	2.0	39
3	Starboard Checkout Area	84	87	3.0	45
4	Wing and Fin Assembly Area	76	95	19.0	See Figure 5.
5	After Repair Station No. 3	80	82.5	2.5	116
6	After Repair Station No. 3	79	80	1.0	106

TABLE 3 RESULTS OF GAS SAMPLING TESTS

Test No.	Type of Sample	No. of Samples	Sampling Area	Access or Sampling Time	Concentration	Remarks
1	Carbon Monoxide	1	Missile House near Observation Port.	X to X+20 Sec.	40 ppm	
		1	Missile House near Observation Port.	X+20 Sec.	25 ppm	Smoke in area.
		2	Missile House near Observation Port.	X+22 Sec. Avg.	10 ppm	Smoke in area.
		1	Portside of Missile House.	X+17 Sec.	10 ppm	Smoke in area.
		1	Portside of Missile House.	X+22 Sec.	Less than 10 ppm	Smoke in area.
		1	Starboard side of Missile House.	X+21 Sec.	Less than 10 ppm	Smoke around Starboard Blast Door.
		1	CPO Living Space at intake vent.	X+15 Sec.	Less than 10 ppm	Odor of smoke.
	Lead (M-S-A)	3	Missile House near Observation Port.	X+22 Sec. Avg.	.20 mg/m ³	Smoke in area.
	Lead (M-S-A)	1	Missile House near Observation Port.	X+5 Min.	.05 mg/m ³	
	Lead (M-S-A)	3	CPO Living Space at intake vent.	X+15 Sec. Avg.	No trace	Odor of smoke.
	Lead (Eythl)	1	Missile House near Observation Port.	X to X+5 Min.	.32 mg/m ³	Smoke in area.
	Oxides of Nitrogen	1	CPO Living Space at intake vent.	X+15 Sec.	No trace	Odor of smoke.
	Oxides of Nitrogen	1	Missile House near Observation Port.	X+22 Sec.	No trace	Smoke in area.
2	Carbon Monoxide	1	Port Checkout Area.	X to X+20 Sec.	Less than 10 ppm	
		1	Port Checkout Area.	X+38 Sec.	Less than 10 ppm	
		1	Portside of Missile House.	X+18 Sec.	Less than 10 ppm	
		1	CPO Living Space at intake vent.	X+11 Sec.	Less than 10 ppm	
	Lead (M-S-A)	3	Port Checkout Area.	X+30 Sec. Avg.	No trace	
	Lead (M-S-A)	3	CPO Living Space at intake vent.	X+11 Sec. Avg.	No trace	
	Lead (Eythl)	1	Port Checkout Area.	X to X+5 Min.	.23 mg/m ³	
	Oxides of Nitrogen	1	CPO Living Space at intake vent.	X+11 Sec.	No trace	
	Oxides of Nitrogen	1	Port Checkout Area.	X+30 Sec.	No trace	

TABLE 3 (Continued)

Test No.	Type of Sample	No. of Samples	Sampling Area	Access or Sampling Time	Concentration	Remarks
3	Carbon Monoxide	1	CPO Living Space at exhaust vent.	X+10 Sec.	Less than 10 ppm	Smoke coming through exhaust vent.
		1	Starboard side of Missile House.	X+20 Sec.	Less than 10 ppm	Odor of smoke.
		1	Starboard Checkout Area.	X+28 Sec.	Less than 10 ppm	Odor of smoke.
		1	Starboard side of Missile House.	X to X+20 Sec.	Less than 10 ppm	Odor of smoke.
	Lead (M-S-A)	3	CPO Living Space at exhaust vent.	X+20 Sec. Avg.	.40 mg/m ³	Smoke coming through exhaust vent.
		3	CPO Living Space at intake vent.	X+10 Sec. Avg.	No trace	
		3	Starboard Checkout Area.	X+28 Sec. Avg.	No trace	
		1	Starboard Checkout Area.	X to X+5 Min.	.30 mg/m ³	
		1	Starboard Checkout Area.	X+28 Sec.	No trace	Odor of smoke.
		2	CPO Living Space.	X+10 Sec. Avg.	No trace	
4	Carbon Monoxide	1	CPO Living Space at exhaust vent.	X+9 Sec.	Less than 10 ppm	Area filled with smoke.
		1	Starboard Wing and Fin Area.	X+12 Sec.	Less than 10 ppm	Smoke in area near Starboard Blast Door.
	Lead (Y-S-A)	1	Missile House near Starboard Blast Door.	X+12 Sec.	Less than 10 ppm	Smoke in area.
		1	Missile House near Starboard Blast Door.	X to X+2 Min.	Less than 10 ppm	
	Lead (M-S-A)	3	CPO Living Space.	X+9 Sec. Avg.	No trace	
		3	Missile House near Starboard Blast Door.	X+17 Sec. Avg.	No trace	
	Lead (Eythl)	1	Missile House near Starboard Blast Door.	X to X+5 Min.	.27 mg/m ³	
		1	Starboard Wing and Fin Area.	X+17 Sec.	No trace	
	Oxides of Nitrogen	1	CPO Living Space.	X+9 Sec.	No trace	

TABLE 3 (Continued)

Test No.	Type of Sample	No. of Samples	Sampling Area	Access or Sampling Time	Concentration	Remarks
5	Carbon Monoxide	1	CPO Living Space at exhaust vent.	X+10 Sec.	Less than 10 ppm	
		1	Below Hatch H-1-136-1.	X+15 Sec.	Less than 10 ppm	
		1	Starboard Side of Wing and Fin Area.	X+15 Sec.	Less than 10 ppm	
		1	Starboard Side of Wing and Fin Area.	X to X+2 Min.	Less than 10 ppm	
		1	Aft Repair #3.	X+15 Sec.	10 ppm	
		1	Aft Repair #3.	X to X+2 Min.	10 ppm	
		3	CPO Living Space.	X+10 Sec. Avg.	No trace	
		3	Missile House near Starboard Blast Door.	X+11 Sec. Avg.	No trace	
		1	CPO Living Space at intake vent.	X to X+5 Min.	No trace	
		1	CPO Living Space.	X+10 Sec.	No trace	
6	Carbon Monoxide	1	CPO Living Space at exhaust vent.	X+10 Sec.	Less than 10 ppm	
		1	Below Hatch H-1-130-2.	X+16 Sec.	Less than 10 ppm	
		1	Portside of Wing and Fin Area.	X+13 Sec.	Less than 10 ppm	
		1	Aft Repair #3.	X+15 Sec.	Less than 10 ppm	
		1	Below Hatch H-1-130-2.	X to X+2 Min.	Less than 10 ppm	
		1	Portside of Missile House.	X to X+2 Min.	Less than 10 ppm	
		3	Below Hatch H-1-130-2.	X+16 Sec. Avg.	No trace	
		3	CPO Living Space	X+10 Sec. Avg.	No trace	
		1	CPO Living Space at exhaust vent.	X to X+5 Min.	No trace	
		1	CPO Living Space	X+10 Sec.	No trace	
7	Oxides of Nitrogen	1	Hatch H-1-130-2.	X+18 Sec.	No trace	

TABLE 4 MAXIMUM NOISE LEVELS MEASUREMENTS

<u>Test No.</u>	<u>Location</u>	<u>No. in Figure 1</u>	<u>Maximum Noise Level, db with respect to 0.0002 dyne/cm²</u>
1	Port Sky Lookout	7	124
	Port Checkout	3	127
	Observation Port	2	127
2	Port Sky Lookout	7	129
	Port Checkout	3	128
	Port Wing and Fin Assembly	4	119
	Aft Repair Station No. 3	1	Over 100
	Starboard Checkout	6	122
3	Starboard Sky Lookout	8	123
	Starboard Checkout	6	128
	Starboard Wing and Fin Assembly	5	121
	Port Checkout	3	130
	Aft Repair Station No. 3	1	122
4	Starboard Sky Lookout	8	125
	Starboard Checkout	6	125
	Observation Port	2	122
	Starboard Wing and Fin Assembly	5	132
	Aft Repair Station No. 3	1	124
5	Starboard Sky Lookout	8	124
	Aft Repair Station No. 3	1	119
		1	

TABLE 4 (Continued)

<u>Test No.</u>	<u>Location</u>	<u>No. in Figure 1</u>	<u>Maximum Noise Level, db with respect to 0.0002 dyne/cm²</u>
5	Observation Port	2	120
	Starboard Checkout	6	129
6	Starboard Sky Lookout	8	124
	Aft Repair Station No. 3	1	113
	Observation Port	2	122

TABLE 5 PRESSURE MEASUREMENTS ON MISSILE HOUSE

<u>Test No.</u>	<u>Location</u>		<u>Peak Pressure (psig)</u>	
	<u>Frame No.</u>	<u>Height Above Deck</u>	<u>Positive</u>	<u>Negative</u>
2	121.5	48"	13	3
	120.5	34"	14	7
	119.25	21"	13	4
	118.5	15"	12	4
	117.5	15"	**	**
	113.5	15"	**	**
	109.5	15"	**	**
	109.5	11'0"	**	**
3	121.5	48"	10	11
	120.5	34"	2	1
	119.25	21"	13	1
	118.5	15"	13	*
	117.5	15"	5	3
	113.5	15"	3	2
	109.5	15"	3	2
	109.5	11'0"	4	1

* No pressure
 ** No record

TABLE 6 **PRESSURE MEASUREMENTS ON THE DECK**

<u>Test No.</u>	<u>Location</u>		<u>Peak Pressure (psig)</u>	
	<u>Gauge No.</u>	<u>Figure No.</u>	<u>Positive</u>	<u>Negative</u>
5	1	4	15	8
	2	4	27	7
	3	4	5	6
	4	4	270	*
	5	4	115	*
	6	4	40	*
	7	4	90	*
	8	4	145	*
	9	4	100	*
	10	4	250	*
6	1	3	30	*
	2	3	145	*
	3	3	210	*
	4	3	125	*
	5	3	90	*
	6	3	165	*
	7	3	30	*
	8	3	10	*
	9	3	70	*
	10	3	130	*
	11	3	25	*


* No pressure detected

TABLE 7 FLAME INDICATOR RESULTS FOR ALL ROUNDS

<u>Test No.</u>	<u>Location</u>	<u>Locations as Shown on Figure 7</u>	<u>Results</u>
1	Port Blast Door	P1 thru P7	No physical damage.
		P8	Partially hard, discolored and burned.
		P9	Partially hard, discolored and burned.
		P12	Partially discolored and burned.
		P13	Partially hard, discolored and burned.
		P14	Partially hard, discolored and burned.
		P15 thru P18	Missing. Two tufts, tape and small residue of cloth, were found on the deck.
		P19	30% of cloth destroyed, remaining cloth forming hard mass.
		P20	Partially discolored.
		P21	Partially discolored.
2	All Doors	All tufts	No physical damage.
3	All Doors	All tufts	No physical damage.


TABLE 7 (Continued)

<u>Test No.</u>	<u>Location</u>	<u>Locations as Shown on Figure 7</u>	<u>Results</u>
4	Starboard Blast Door	S6	Partially discolored and burned.
		S7	Tape and small residue of cloth remaining.
		S8	Partially hard, discolored and burned.
		S9	75% hardened and discolored.
		S11	Tape and small residue of cloth remaining.
		S12	Missing or completely destroyed.
		S13	Partially discolored.
		S18	Partially discolored.
		S19	Partially hard, discolored and burned.
5	All Doors	All tufts	No physical damage.
6	All Doors	All tufts	No physical damage.



Microphone Locations

Figure 1



PRESSURE AND STRAIN GAUGE LOCATIONS ON STARBOARD SIDE OF MISSILE HOUSE

Figure 2




Figure 3

Arrangement of Holes in Main Deck for Pressure Measurements in the Exhaust Stream for High Angle Launchings (45° Elevation Shown).

Longitudinal axis of missile when on launcher intersects pattern at center and lies in a plane vertical to paper and including line AB.





Figure 4

Arrangement of Holes in Main Deck for Pressure Measurements in the Exhaust Stream for High Angle Launchings (75° Elevation Shown).

Longitudinal axis of missile when on launcher intersects pattern at center and lies in a plane vertical to paper and including line AB.



TEMPERATURE TIME CURVE FOR TEST 4 STARBOARD WING AND FIN AREA

Figure 5





Figure 6

Strain Record for Test 3

- 1 - Top Gauge
- 2 - Center Gauge
- 3 - Bottom Gauge

INTERIOR PROFILE OF BLAST DOOR




FLAME INDICATOR LOCATIONS

Note: Port Blast Door locations are the same as Starboard Blast Door.

Symbols: P - Port Blast Door
S - Starboard Blast Door

Figure 7




PFD-84640-8-60

Figure 8
Impingement Area
Test 1

29 August 1960

1. The blacken area beneath the observer's port indicates the impingement area for Test 1.
2. There was no apparent structural damage observed during the tests.



PED-84641-8-60


Figure 9

Port Blast Door Seals

Test 1 (Continued)

3. There was severe leakage of gas, flame, and smoke past the seals of the port blast door.
4. The blacken areas on the blast door and the blast door frame indicate where leakage occurred past seals of the port blast door.

28 August 1960



PHD-84642-8-60



Figure 10

Leakage Around Port Blast Door

Test 1 (Continued)

1. The above photographs are enlargements printed from 16mm motion picture film taken during Test 1 of the leakage around the port blast door.
2. The sequence was taken at approximately 1/15 second intervals and run from left to right with the first photograph showing the door prior to the firing.

29 August 1960



PHD-84643-8-60

29 August 1960

Figure 11
Leakage Around Port Blast Door
Test 1 (Continued)

3. Note that the leakage starts in the upper left corner of the door and progresses around the door.
4. The last photograph shows only smoke entering around the top of the door which continued for approximately .5 of a second longer.



Wooden Deck Burned

PHD-84644-8-60



Impingement Area Test 2

29 August 1960

Figure 12
Test 2

1. The wooden deck was slightly burned forward to Frame 109.
2. The sheet metal protective plate for the boat boom switch 6FB-104-06 on the main deck at Frame 119 portside was severely bent forward.
3. One of the drain pipe hangers on the slanting bulkhead was bent forward.



Scorched Fire Hose

PHD-84645-8-60




Damaged Inspection Plate

Figure 13

29 August 1960

Test 2 (Continued)

4. The inspection plate for ventilation reheat 167P C-202-L at Frame 115, in the overhead of the CPO mess, sheared the stud bolts holding it to the reheat on three sides.
5. The blow-out patch at Frame 109 portside was dimpled slightly and separated from its inner seat.
6. The fire hose located at Frame 117 portside was slightly scorched by flame which leaked past the metal fire hose cover.



Damaged Boat Boom Switch




Broken Drain Pipe Hanger

PHD-84646-8-60

Figure 14
Test 3


28 August 1960

1. The boat boom switch at Frame 119 was severely bent forward and damaged.
2. A boat boom stanchion and brace located just after of the boat boom switch was torn from the deck and thrown forward to Frame 91 causing gouges in the teak wood decking.
3. The life line stanchion at Frame 115 was bent forward.
4. The bottom drain pipe hanger at Frame 117 sheared the fastening bolt of the clamp.



Stanchion from Frame 119

PHD-84647-8-60



Damaged Stanchion Brace

29 August 1960

Figure 15
Test 3 (Continued)

5. The washdown countermeasures nozzle at the top of the missile house, 02 level starboard side Frame 120, was broken off.
6. The blow-out patch at Frame 109 starboard was slightly dislodged.




PHD-84430-8-60

Figure 16

Impingement Areas for Tests 1 and 4
Test 4

30 August 1960

1. The washdown sprinkler head located above the starboard blast door was carried away by the blast.
2. There was severe gas and flame leakage past the seals of the starboard blast door.



PED-84643-8-60

Figure 17

30 August 1960

Leakage Around the Starboard Blast Door

Test 4 (Continued)

1. The above photographs are enlargements printed from 16mm motion picture film taken during Test 4 of the leakage around the starboard blast door.
2. The sequence was taken at approximately 1/15 second intervals and run from left to right.
3. Note that most of the leakage occurred along the right side of the door close to the impingement area.
4. The first photograph shows the door prior to the firing and the last shows only the smoke entering which continued for approximately .3 of a second after the firing.




PHD-84339-8-60

Figure 18
Impingement Area for Test 6
Test 6

30 August 1960

1. There was no apparent damage incurred during this test.
2. The above photograph shows the holes used to obtain pressure measurements during Test 6. See Figure 3.




30 August 1960

PHD-84340-8-60

Figure 19
Impingement Area for Test 5.

Test 5

1. There was no apparent damage incurred during this test.
2. The above photographs shows the holes used to obtain pressure measurements during Test 5. See Figure 5.



PHD-84431-8-60

Figure 20

30 August 1960

View of the launcher area at completion of all the tests.

APPENDIX A

DETAILED TEST OBJECTIVES

Test No. 1:

Condition: "A" rail loaded. Train 144⁰⁴⁴' Elevation 14°.

Impingement Point Location: Center of the Observation Port.

- Objectives:**
- (1) To test structural strength of the Observation Port in the sloping bulkhead of the missile deck house to withstand booster blast.
 - (2) To determine the blast effects of an oblique blast on the blast doors and their seals.
 - (3) To determine effect of blast spillover on #2 AN/SPG-49 antenna, mountings and exposed machinery.
 - (4) To test safe habitability of missile deck house during missile firings.

Test No. 2:

Condition: "B" rail loaded. Train 156⁰⁰⁵' Elevation 12°30'.

Impingement Point Location: Two feet aft of Port Checkout Door (D-1-119-2) on slanting bulkhead 2'3" above main deck.

- Objectives:**
- (1) To test blast effects on Port Checkout Compartment Door (D-1-119-2) and on the deck house slanting bulkhead.
 - (2) To determine blast effects on blow-out patches and vent intakes.
 - (3) To determine blast effects on equipment mounted on the side of the missile house.
 - (4) To test safe habitability of missile deck house during missile firings.
 - (5) To obtain pressure information in a region where severe gas and flame entry have been observed on another ship of similar design.

DETAILED TEST OBJECTIVES (Continued)

Test No. 3:

Condition: "A" rail loaded. Train 207°59' Elevation 10°53'.

Impingement Point
Location:

Main Deck Frame 121 starboard side.

Objectives:

- (1) To test blast effects on the Starboard Check-out Compartment Door (D-1-119-1).
- (2) To determine blast effects on the blow-out patches and the exhaust vents.
- (3) To determine blast effects on equipment mounted on the side of the missile house.
- (4) To test safe habitability of the missile deck house during missile firings.
- (5) To obtain pressure information in the region where severe gas and flame entry have been observed on another ship of similar design.

Test No. 4:

Condition: "B" rail loaded. Train 220°59' Elevation 10°.

Impingement Point
Location:

Inboard edge of the starboard blast door.

Objectives:

- (1) To determine the blast effects on the blast door and their seals from a shot wherein the booster blast strikes the blast door at an acute angle.
- (2) To determine effect of blast spillover on #2 AN/SPG-49 antenna, mountings and exposed machinery.
- (3) To determine safe habitability of missile deck house during missile firings.

DETAILED TEST OBJECTIVES (Continued)

Test No. 5:

Condition: "A" rail loaded. Train 145° Elevation 75°.

Impingement Point
Location: Main deck beneath the launcher (high angle).

- Objectives:
- (1) To determine the blast effects on the bolt locking devices around the base ring of the launcher.
 - (2) To determine the blast effects on the emergency igniter injector unit.
 - (3) To collect pressure data at the impingement area.

Test No. 6:

Condition: "A" rail loaded. Train 39° Elevation 43°.

Impingement Point
Location: Deck aft of launcher so that the flame and hot gases pass over Hatch (H-1-130-2).

- Objectives:
- (1) To test for gas and flame tightness of Hatch (H-1-130-2).
 - (2) To determine safe habitability of second deck level for personnel who will man the Aft Repair Station #3 and Secondary Control Station.
 - (3) To determine the blast effects on the radar antennas, mountings and exposed machinery from a missile passing close by.
 - (4) To collect pressure data at the impingement area.

APPENDIX B

DISTRIBUTION

Bureau of Naval Weapons:

DIS-31	4
RM-2	1
RM-15	1
RM-27	1
C-15	1
RSWI	1
RMGA-22	1
RMMP	1
RMLG-2	1
FWSE	1

Commander
 Armed Services Technical Information Agency
 Arlington Hall Station
 Arlington 12, Virginia
 Attn: TIPDR 10

Commanding General
 Aberdeen Proving Ground
 Aberdeen, Maryland
 Attn: Technical Information Section
 Development and Proof Services 2

Commander, Operational Test and Evaluation Force
 U. S. Atlantic Fleet, U. S. Naval Base
 Norfolk 11, Virginia 2

Office of Technical Services
 Department of Commerce
 Washington 25, D. C. 1

Bureau of Ships:

Code 423	1
Code 442	1
Code 443	1
Code 523	1
Code 633	1
Code 635	1

DISTRIBUTION (Continued)

Naval Weapons Plant:	
Code 300	1
Code 700	1
Code 173	1
Naval Weapons Services Office	
Code 230	
Naval Weapons Plant	
Washington 25, D. C.	2
U. S. Naval Shipyard	
Puget Sound, Washington	
Attn: Design Superintendent	1
Attn: Ordnance Superintendent	1
Boston Naval Shipyard	
Boston, Massachusetts	
Attn: Code 253	1
Attn: Ordnance Superintendent	1
New York Naval Shipyard	
New York, New York	
Attn: Design Superintendent	1
Attn: Ordnance Superintendent	1
U. S. Naval Shipyard	
San Francisco, California	
Attn: Design Superintendent	1
Attn: Ordnance Superintendent	1
U. S. Naval Shipyard	
Philadelphia, Pennsylvania	
Attn: Design Superintendent	1
Attn: Ordnance Superintendent	1
Bethlehem Steel Company	
Quincy, Massachusetts	
Attn: Supervisor of Shipbuilding	2
Bath Iron Works	
Bath, Maine	
Attn: Supervisor of Shipbuilding	2

DISTRIBUTION (Continued)

New York Shipbuilding Corporation Camden, New Jersey Attn: Supervisor of Shipbuilding	2
Puget Sound Bridge and Dry Dock Company Seattle, Washington Attn: Supervisor of Shipbuilding	2
Todd Shipyard Corporation San Pedro, California Attn: Supervisor of Shipbuilding	2
Commanding Officer USS LITTLE ROCK (CLG-4) c/o Fleet Post Office New York, New York	2
Commanding Officer USS GALVESTON (CLG-3) c/o Fleet Post Office New York, New York	2
Commanding Officer USS OKLAHOMA CITY (CLG-5) c/o Fleet Post Office San Francisco, California	2
Prospective Commanding Officer USS LONG BEACH (CGN-9) Bethlehem Steel Company Quincy, Massachusetts	2
Prospective Commanding Officer USS ALBANY (CG-10) Boston Naval Shipyard Boston, Massachusetts	2
CONVAIR Pomona, California	1
Commander U. S. Naval Ordnance Test Station China Lake, California	1

DISTRIBUTION (Continued)

U. S. Naval Inspector of Ordnance, APL/JHU	1
Commanding Officer U. S. Naval Ordnance Laboratory Corona, California Attn: Documents Library	2
Alleghany Ballistics Laboratory Cumberland, Maryland Attn: Mr. Donald Black	1
Commander, Destroyer Force U. S. Atlantic Fleet c/o Fleet Post Office New York, New York	5
Commander-in-Chief U. S. Atlantic Fleet c/o Fleet Post Office New York, New York	1
Commander, Cruiser Force U. S. Atlantic Fleet c/o Fleet Post Office New York, New York	2
Commander, Cruiser Destroyer Force U. S. Pacific Fleet c/o Fleet Post Office San Francisco, California	2
Commander, Training Command U. S. Atlantic Fleet c/o Fleet Post Office New York, New York	1
Officer-in-Charge Guided Missile Evaluation Unit No. 1 Naval Air Station, North Island San Diego 35, California	1
APL/JHU Silver Spring, Maryland	4

DISTRIBUTION (Continued)

Vitro Corporation of America 14000 Georgia Avenue Silver Spring, Maryland Attn: Librarian	3
Northern Ordnance Inc. Minneapolis, Minnesota Via: U. S. Naval Inspector of Ordnance Northern Pump Company Minneapolis, Minnesota	2
U. S. Atomic Energy Commission Sandia Corporation Albuquerque, New Mexico	1
Chief of Naval Operations:	
OP-34	1
OP-51	1
OP-91	1
Bureau of Medicine and Surgery	
Code 73	1
Local:	
WX	2
WDC	1
WDEP	6
W	1
WD	1
WDE	1
ACL	5
File	1

<p>Naval Weapons Lab. (NWL_Report No. 1751) TALOS STRUCTURAL FIRING TEST ABOARD THE USS LITTLE ROCK (CLG-4), by J. W. Lovino, T. I. Dodson, C. W. Fischler and P. E. Wine. 11 May 1961. 11 p., 20 figs., 7 tables. UNCLASSIFIED</p> <p>The results indicated gas and flame leakage around the blast doors, toxic gas leakage into the ventilation systems, and minor structural damage to equipment mounted on the sides of the missile house and the main deck. A detailed description of all data obtained and ship damage incurred is included.</p>	<p>i. Guided missiles - Test results I. Lovino, J. W. II. Dodson, T. I. III. Fischler, C. W. IV. Wine, P. E. V. TALOS VI. USS LITTLE ROCK</p> <p>Task: NO 512-535/55008/ 59-084</p> <p>UNCLASSIFIED</p>	<p>Naval Weapons Lab. (NWL_Report No. 1751) TALOS STRUCTURAL FIRING TEST ABOARD THE USS LITTLE ROCK (CLG-4), by J. W. Lovino, T. I. Dodson, C. W. Fischler and P. E. Wine. 11 May 1961. 11 p., 20 figs., 7 tables. UNCLASSIFIED</p> <p>The results indicated gas and flame leakage around the blast doors, toxic gas leakage into the ventilation systems, and minor structural damage to equipment mounted on the sides of the missile house and the main deck. A detailed description of all data obtained and ship damage incurred is included.</p>	<p>i. Guided missiles - Test results I. Lovino, J. W. II. Dodson, T. I. III. Fischler, C. W. IV. Wine, P. E. V. TALOS VI. USS LITTLE ROCK</p> <p>Task: NO 512-535/55008/ 59-084</p> <p>UNCLASSIFIED</p>
<p>Naval Weapons Lab. (NWL_Report No. 1751) TALOS STRUCTURAL FIRING TEST ABOARD THE USS LITTLE ROCK (CLG-4), by J. W. Lovino, T. I. Dodson, C. W. Fischler and P. E. Wine. 11 May 1961. 11 p., 20 figs., 7 tables. UNCLASSIFIED</p> <p>The results indicated gas and flame leakage around the blast doors, toxic gas leakage into the ventilation systems, and minor structural damage to equipment mounted on the sides of the missile house and the main deck. A detailed description of all data obtained and ship damage incurred is included.</p>	<p>i. Guided missiles - Test results I. Lovino, J. W. II. Dodson, T. I. III. Fischler, C. W. IV. Wine, P. E. V. TALOS VI. USS LITTLE ROCK</p> <p>Task: NO 512-535/55008/ 59-084</p> <p>UNCLASSIFIED</p>	<p>Naval Weapons Lab. (NWL_Report No. 1751) TALOS STRUCTURAL FIRING TEST ABOARD THE USS LITTLE ROCK (CLG-4), by J. W. Lovino, T. I. Dodson, C. W. Fischler and P. E. Wine. 11 May 1961. 11 p., 20 figs., 7 tables. UNCLASSIFIED</p> <p>The results indicated gas and flame leakage around the blast doors, toxic gas leakage into the ventilation systems, and minor structural damage to equipment mounted on the sides of the missile house and the main deck. A detailed description of all data obtained and ship damage incurred is included.</p>	<p>i. Guided missiles - Test results I. Lovino, J. W. II. Dodson, T. I. III. Fischler, C. W. IV. Wine, P. E. V. TALOS VI. USS LITTLE ROCK</p> <p>Task: NO 512-535/55008/ 59-084</p> <p>UNCLASSIFIED</p>

TALOS STRUCTURAL FIRING TEST ABOARD THE USS LITTLE ROCK (CLG-4).

NWL REPORT NO. 1751